



Versandanschrift
 Address
 Adresse du destinataire
 Indirizzo di trasporto
 Dirección de expedición

Fax.-No

Ersatzteilliste
 Spare parts list
 Liste des pièces de rechange
 Elenco parti di ricambio
 Lista de piezas de repuesto

| | | | |
|---------|----------------------------------|-----|--------------|
| 1207353 | TruTool TKA 300 (1A1) | D | 230V 50/60Hz |
| 1209269 | | CH | 230V 50/60Hz |
| 1214434 | | GB | 110V 50Hz |
| 1209270 | | USA | 120V 50/60Hz |
| 1235645 | | PL | 230V 50-60Hz |

| NO. D'ORDINE NO. DE REF. NO. DE REF. ORDER. NO. NO | BEST.-NR. | PEZZO DI RICAMBIO PIEZA DE RECAMBIO PIECE DE RECHANGE SPARE PART ERSATZTEIL | DIN | QUAN. CANT. QUAN. QUAN. STK. |
|--|-----------|---|----------|--|
| 1 | 0117039 | M8X30-8.8 verz. | DIN 912 | |
| 2 | 0207428 | 8,4-ST | DIN 433 | |
| 3 | 1209000 | | | |
| 4 | 1209003 | | | |
| 5 | 0017159 | M8x20-8.8 | ISO 4017 | |
| 6 | 0353387 | | | |
| 7 | 1209676 | ST SET | | |
| 8 | 1214439 | D22; 45°/55°/60° | | |
| 9 | 0022330 | M6-10 | ISO 4032 | |
| 10 | 1223697 | 45° | | |
| 11 | 1646214 | | | |
| 12 | 1208984 | | | |
| 13 | 1208985 | | | |
| 14 | 1282892 | | | |
| 15 | 1208987 | | | |
| 16 | 0353514 | | | |
| 17 | 1208988 | | | |
| 18 | 0353932 | M3x3-A2F | ISO 4766 | |

| | | | | |
|----|---------|------------------|---------|--|
| 19 | 0028185 | 40x1,75-FDST | DIN 472 | |
| 20 | 0353533 | | | |
| 21 | 0353384 | | | |
| 22 | 1214438 | | | |
| 23 | 1208955 | | | |
| 24 | 1208956 | | | |
| 25 | 1214436 | | | |
| 26 | 0353888 | | | |
| 27 | 1207364 | D 230V 50/60Hz | | |
| | 1207364 | CH 230V 50/60Hz | | |
| | 1209279 | GB 110V 50Hz | | |
| | 1209279 | USA 120V 50/60Hz | | |
| 28 | 0354059 | | | |
| 29 | 0980416 | D, CH, GB, PL | | |
| | 1265591 | USA | | |
| 30 | 0353393 | D 230V 50/60Hz | | |
| | 1209278 | CH 230V 50/60Hz | | |
| | 1213668 | GB 110V 50Hz | | |
| | 0353430 | USA 120V 50/60Hz | | |
| 31 | 1261375 | USA | | |
| 32 | 0143643 | USA | | |
| 33 | 0359398 | USA | | |
| 34 | 1465246 | | | |

